

February 17, 2010

We are sorry to announce that we have discontinued the 15u and 30u options of the following parts. If required, we could supply the parts, but a high MOQ may apply.

KF88X-AC-15P-15	KF88X-BC-25P-15	KF88X-CC-37P-15	KF88X-EC-9P-15
KF88X-AC-15P-30	KF88X-BC-25P-30	KF88X-CC-37P-30	KF88X-EC-9P-30
KF88X-AC-15P-BR15	KF88X-BC-25P-BR15	KF88X-CC-37P-BR15	KF88X-EC-9P-BR15
KF88X-AC-15P-BR30	KF88X-BC-25P-BR30	KF88X-CC-37P-BR30	KF88X-EC-9P-BR30
KF88X-AC-15P-BRJ15	KF88X-BC-25P-BRJ15	KF88X-CC-37P-BRJ15	KF88X-EC-9P-BRJ15
KF88X-AC-15P-BRJ30	KF88X-BC-25P-BRJ30	KF88X-CC-37P-BRJ30	KF88X-EC-9P-BRJ30
KF88X-AC-15P-K15	KF88X-BC-25P-K15	KF88X-CC-37P-K15	KF88X-EC-9P-K15
KF88X-AC-15P-K30	KF88X-BC-25P-K30	KF88X-CC-37P-K30	KF88X-EC-9P-K30
KF88X-AC-15P-KJ15	KF88X-BC-25P-KJ15	KF88X-CC-37P-KJ15	KF88X-EC-9P-KJ15
KF88X-AC-15P-KJ30	KF88X-BC-25P-KJ30	KF88X-CC-37P-KJ30	KF88X-EC-9P-KJ30
KF88X-AC-15P-R15	KF88X-BC-25P-R15	KF88X-CC-37P-R15	KF88X-EC-9P-R15
KF88X-AC-15P-R30	KF88X-BC-25P-R30	KF88X-CC-37P-R30	KF88X-EC-9P-R30
KF88X-AC-15S-15	KF88X-BC-25S-15	KF88X-CC-37S-15	KF88X-EC-9S-15
KF88X-AC-15S-30	KF88X-BC-25S-30	KF88X-CC-37S-30	KF88X-EC-9S-30
KF88X-AC-15S-BR15	KF88X-BC-25S-BR15	KF88X-CC-37S-BR15	KF88X-EC-9S-BR15
KF88X-AC-15S-BR30	KF88X-BC-25S-BR30	KF88X-CC-37S-BR30	KF88X-EC-9S-BR30
KF88X-AC-15S-BRJ15	KF88X-BC-25S-BRJ15	KF88X-CC-37S-BRJ15	KF88X-EC-9S-BRJ15
KF88X-AC-15S-BRJ30	KF88X-BC-25S-BRJ30	KF88X-CC-37S-BRJ30	KF88X-EC-9S-BRJ30
KF88X-AC-15S-K15	KF88X-BC-25S-K15	KF88X-CC-37S-K15	KF88X-EC-9S-K15
KF88X-AC-15S-K30	KF88X-BC-25S-K30	KF88X-CC-37S-K30	KF88X-EC-9S-K30
KF88X-AC-15S-KJ15	KF88X-BC-25S-KJ15	KF88X-CC-37S-KJ15	KF88X-EC-9S-KJ15
KF88X-AC-15S-KJ30	KF88X-BC-25S-KJ30	KF88X-CC-37S-KJ30	KF88X-EC-9S-KJ30
KF88X-AC-15S-R15	KF88X-BC-25S-R15	KF88X-CC-37S-R15	KF88X-EC-9S-R15
KF88X-AC-15S-R30	KF88X-BC-25S-R30	KF88X-CC-37S-R30	KF88X-EC-9S-R30